

Attachment A: Digital Images

Page 1 of 11

May 21st, 2008 Assessment

BOE 22nd Floor Break Room 2202, 2223, and 2224 Clearance
Sacramento, CA



- 1) Image of ambient air sampling location at rooftop of garage structure adjacent to the BOE building (Subject Building) located at 450 N Street, Sacramento.



- 2) Image of air sampling equipment located within hallway of 22nd Floor near 2202 break room containment.



- 3) Image of wall removal delineation and air sampling activity performed within Break Room 2202 at time of assessment.



- 4) Image of adjacent wallboard removal delineation performed within Break Room 2202 as part of mitigative activity.



- 5) Image of BioMax and HTI air sampling equipment oriented within Break room 2223 at time of assessment.



- 6) Image of wallboard removal delineation performed within 2223 at time of assessment.



- 7) Additional perspective image indicating extent of wallboard removal performed within break room 2223 as part of the mitigative activity.



- 8) Image of wallboard removal delineation performed within Employee Lounge (Break Room 2224) as part of the mitigative efforts.



- 9) Image of baseboard removal performed within 2224 at structural support chase area. No visual indications of staining were observed at the time of assessment.



- 10) Image of air sampling activity performed in hallway adjacent to 2223 and 2224 containment areas.



11) Image of ambient air sample location on 23rd floor northern balcony following the sample collection of interior samples.



12) Image of air sampling performed within hallway near men's restroom area at time of assessment.



13) Image of wallboard removal and exposed plumbing within men's restroom area following mitigative activity.



14) Close up image of paper towel chase and interior plumbing systems located to the right of sink area within men's restroom following mitigative activity.



15) Close-up image of wall surface behind right-side paper towel cavity. Noted absence of elevated staining present on wall surface leading to elevator shaft.



16) Close up image of exposed plumbing and metal framing located at sink area within men's restroom following mitigative removal.



17) Close-up image of wallboard material to left side of prior sink cabinet location. Absence of elevated staining present on wallboard adjacent to elevator shaft system.




18) Image of BioMax and HTI air sampling activities performed within women's restroom containment area at time of assessment.



19) Image of plumbing structures and underlayment materials within women's restroom containment area at time of assessment.



20) Close up image of exposed wallboard material to right of prior sink cabinet location of women's restroom. Absence of elevated staining noted on wall surface.



21) Image of "paper towel" cavity to left of prior sink within women's restroom area. Absence of elevated staining noted on underlayment wall surface adjacent to elevator shaft.